

Date	Mileage	Oil	Topic		Cost
06/02/2005	1,164	✓	1200 mile service, oil	Inspection	
11/01/2005	4,271	☐	BMW CCA tech insp., changed differential oil, changed transmission oil	Other	
03/02/2006	6,931	✓	oil & filter, change transmission oil	Oil	
05/01/2006		☐	mount tires	Tires	
06/09/2006	10,180	☐	alignment & check corner weight	Alignment	
06/09/2006	10,179	✓	oil, filter, interior air filter, washer fluid	Oil	
07/19/2006	11,000	☐	front control arm bushings upgrade to GC, trailing arm bushings upgrade to Powerflex, check front & rear toe	Other	
10/11/2007	20,906	✓	inspection I / oil, filter, microfilter, valve clearance check, ABS fluid flush, windshield wipers replaced, faulty seat rail replaced, dash trim replaced,	Inspection	
11/03/2007	22,168	☐	TCU SIB #84-22-06 & SIB #84-23-06	Warranty Repair	
12/12/2007	22,000	☐	diagnose noise, found debris behind left/front brake rotor & caliper	Other Repair	
12/17/2007		✓	rim repair	Other Repair	
12/21/2007	22,560	☐	mount tires	Tires	
03/04/2008	23,884	☐	remove rear rotors and clean rocks	Other	
05/27/2008	25,856	✓	BMW CCA tech, brake fluid flush, svc ATE Type 200 brake fluid, oil	Oil	
02/24/2009	32,135	☐	mount tires, check alignment	Tires	
03/13/2009	32,659	✓	high-pitch noise during cold start: replaced alternator drive belt tensioner, ribbed v-belt, deflection pulley; oil, windshield wipers, microfilter	Multiple	\$ 0
04/06/2009	33,217	☐	new brakes	Brakes	\$ 0
07/27/2009	35,501	☐	front right wheel bearing - hub assembly replaced	Other Repair	\$ 419
11/18/2009	38,058	☐	corrected backwards rotor installation	Other	\$ 0
11/19/2009	38,070	☐	new battery	Other	\$ 225
02/02/2010	40,386	✓	oil service	Oil	\$ 150
04/01/2010	42,088	☐	mount new tires, alignment, ride height, corner weight	Tires	\$ 752
07/08/2010	44,785	✓	oil service, <b>brake fluid flush</b> w/ATE Type 200 High Temp Brake Fluid, microfilter; reset code: (179) B3 cat. converter conversion bank 2 (2x)	Oil	\$ 333
03/04/2011	53,272	☐	replaced cat converter cyl 4-6 (bank 2)	Warranty Repair	\$ 0
05/13/2011	56,891	✓	<b>Service II, short shift kit</b> , oil svc, replaced <b>fuel filter, air filter, spark plugs, differential oil, transmission oil</b> ; performed <b>valve adjustments, replaced right &amp; left rear control arm</b> , replaced <b>windshield washer pump</b> , replaced <b>drive belts</b>	Multiple	\$ 3,124
10/12/2011	63,663	☐	<b>tires</b> : Michelin Pilot Super Sport	Tires	\$ 1,358
10/31/2011	64,963	✓	oil service, replaced <b>alternator</b> , replaced <b>radiator outlet temp sensor</b> (was leaking), nav update, <b>lubricate sunroof tracks</b> , replaced <b>rear brake pads and rotors</b>	Multiple	\$ 1,677
12/07/2011	66,822	☐	replaced faulty alternator	Other Repair	\$ 0
12/11/2012	76,990	✓	oil	Oil	\$ 161
01/11/2013	77,300	☐	micelin super sport <b>tires, front brakes and rotors</b>	Tires	\$ 2,550
05/13/2013	81,915	✓	<b>Inspection I</b> : oil & filter, int. air filter, adjust valves; replaced worn shifter parts (squeaked); TPM on - set tire pressure, reset light; <b>brake fluid flush</b> ,	Multiple	\$ 825
11/18/2013	89,150	✓	oil & filter, replaced the wiper relay	Oil	\$ 288
12/12/2013	89,647	☐	rear lid panel & bumper repair	Other	\$ 1,000
01/27/2014	91,012	☐	Replaced <b>rear tires</b> Michelin Pilot Supersports, new rear-right wheel, patched front-right tire	Tires	\$ 742

05/13/2014	94,840	<input checked="" type="checkbox"/>	oil service	Tires	\$ 283
08/01/2014	97,814	<input type="checkbox"/>	Oil is leaking from the check valve on the side of the block - replace valve. Replaced right-rear muffler hanger	Other Repair	\$ 363
07/24/2017	106,796	<input checked="" type="checkbox"/>	<b>Service II:</b> changed <b>engine oil, differential oil, manual transmission oil. Valve adjustments.</b> Replaced <b>fuel filter, engine air filter, spark plugs.</b> Replaced <b>catalytic converter S54 Bank 1 and 2.</b> Fixed <b>rattling noise in door.</b> Fixed <b>upper timing chain tensioner rail.</b> <b>Brake fluid flush.</b> Replaced <b>air pump hose.</b>	Multiple	\$ 8,077
09/09/2017	106,855	<input type="checkbox"/>	<b>Tires:</b> Michelin Pilot Sport 4S (30k mile warranty)	Tires	\$ 900
02/13/2018	109,977	<input type="checkbox"/>	<b>Suspension: Ohlins Road &amp; Track</b> installed. Replaced <b>rear trailing arm bushings.</b> <b>Wheel alignment.</b> Subframe mounting is cracking - remove <b>rear subframe, weld</b> cracks at mounting points, weld in reinforcement plates. Replace <b>left rear upper control arm.</b> Replace <b>flex disc.</b> Replace <b>left C pillar.</b> replaced <b>exhaust flange gasket</b> and lubricate flag with copper paste. <b>Brake fluid flush.</b>	Multiple	\$ 6,426
03/07/2019	118,275	<input checked="" type="checkbox"/>	oil & filter	Oil	\$ 309
09/16/2019		<input type="checkbox"/>	front collision repair: bumper	Other	\$ 1,187
10/21/2019	121,360	<input type="checkbox"/>	<b>Muffler hangar, heat shield rattle, C pillar trim</b>	Other Repair	\$ 609
12/19/2019	123,282	<input type="checkbox"/>	<b>Front &amp; Rear Brakes, Caliper Dust Shield, Brake Fluid Flush</b>	Brakes	\$ 2,835
01/14/2020	123,605	<input type="checkbox"/>	<b>Tires:</b> Michelin Pilot Sport 4S (30k mile warranty)	Tires	
04/23/2020	125,721	<input type="checkbox"/>	Recall: Takata Front Pass Air Bag Module	Warranty Repair	\$ 0
10/27/2020	126,239	<input checked="" type="checkbox"/>	Replaced <b>all Ignition Coils. Oil Service.</b>	Multiple	\$ 1,004
05/01/2021	126,515	<input type="checkbox"/>	<b>New Battery</b>	Other	\$ 160