

BMW Service Code List

Code	Description
RECALL CAMPAIGNS	
0011660100	Recall Campaign 02E-A01 SIB 11-09-01 Replace crankcase hose
0012490100	Recall or service update engine electrics
0024230100	Reprogram EGS to correct harsh 3-2, 2-1 downshift per SIB 24-04-03
0034420100	Recall or service update-probably the brake clip
0061420100	Recall 00V-48 SIB 63 02 00 Replace Brake Switch
0061730100	Service Action to Recode Convertible Top Module and IHKA (SIB 61 04 03)
0064330100	recall or service update-air conditioning
0064360100	Recall Campaign 01V-206: Engine Auxiliary/Cooling Fan - E46, E38, E39, E52, E53
0065770100	Recall Campaign 03V-421: Airbag Control Module
ENGINE	
1133043900	Rocker arm/finger/roller-type finger with shaft-unpleasant noises
11360129UW	Camshaft adjusting unit (VANOS)-sticking/jammed
1151013900	Replace water pump
1151014800	Coolant pump--leaking
11530115UW	Thermostat-permanent malfunction
1153129600	Replace thermostat
1172027700	Something with the engine air pump
1172029600	Warning lamp for air pump fault
1172084800	Air pump delivery line (pump to shut off valve) leaking
ENGINE ELECTRICAL SYSTEM	
1214119600	Electronic shift or control units, pulse generator, camshaft, fault code in memory
FUEL PREPARATION SYSTEM	
1390019900	Fuel tank vent valve error, fault in memory.
FUEL SUPPLY	
1611023700	Fuel tank cap loose
1613051400	Fuel ventilation system, emission monitoring, leak, diagnosis unit, occasional malfunction
RADIATOR	
1711075900	Radiator coolant level too low
1778021500	(No 17-78) 17s are cooling system issues.
AUTOMATIC TRANSMISSION	
2400175800	Automatic transmission slipping
FRONT AXLE	
3112043100	Control arms ball joint, excessive play
STEERING	
3221033900	Center track rod unpleasant noises
BRAKES	
34110129UW	Replace left or right front brake caliper (w/o bleeding brakes)
3441073900	Parking brake cable making noise, replaced the rubber grommet to eliminate
3452117900	Replace wheel rotation rate sensor
PEDALS	
3541907100	Replace sticky accelerator pedal SIB 35 01 02
VEHICLE TRIM	
5116051300	Broken front ashtray
5116074100	Body piece replaced
5116331300	Drink holder, front--broken
5116336500	Front drink holder does not lock into position
5116427800	(No 51-16-42) 51-16s are interior trim issues, like the mirror, ash tray, etc.
5121070100	Replace left front door brake (hold-open device)
5124104100	Rear lid catch/lock, rubber buffer poorly adapted/fitted

5131000700	Cracked windshield
5133122900	Front window regulator sticking/jammed
5133123700	Front window regulator, loose
5133123900	Replace left front window regulator
5135001300	Rear window regulator (motor) broken
5135003900	Window regulator, rear--unpleasant noises
5172000100	Edge protection--cracked/broken/torn off
5186022200	Front seat backrest covering fabric manufacturing fault (stitching needed repair)

SEATS

5210013700	Seat rail cover (seat control cover)—loose
------------	--

SLIDING ROOF/FOLDING TOP

5412055200	Replace clips in moonroof shade
5412103700	Remove & replace the moonroof and replace the rubber seal
5431142900	Cover for convertible arms sticking-replaced tension springs pushrods
5434011200	Replace Hydro unit (Z3 folding top)

VEHICLE ELECTRICAL SYSTEM

6113097900	No 61-13-09s but it's for plug/terminal/fuse connections
6121001200	Battery, permanent failure
6130241400	Steering wheel switch malfunction
6131011500	Indicator light switch malfunction
6135671500	Replace the right side mirror module
6166024800	Windscreen washers leaking

INSTRUMENTS, MEASURING SYSTEMS

6214111200	Instrument cluster indicator/warning lights permanent failure
------------	---

LIGHTING

6313051200	Front turn signal lamp failure
6321051200	Rear tail light lamp failure
6321061200	Rear brake light lamp, permanent failure
6325051200	Third brake light, permanent failure
6331023700	Lamp replaced

HEATER AND AIR CONDITIONING

6411127900	Replace heater fan final stage resistor
------------	---

AUDIO, NAVIGATION, ELECTRONIC SYSTEMS

65100215A5	CD Drive-permanent malfunction
------------	--------------------------------

MISCELLANEOUS BODY EQUIPMENT

6763034800	Windshield washer pump leaking
6731905200	Replace moonroof motor module

SEAT BELTS AND ACCESSORIES

7212001200	Replace jack hold-down screw
------------	------------------------------

MAINTENANCE PLAN

34000077MP	Brake fluid flush
34110077MP	Front brake pads replaced under Full Maintenance Program
34117777MP	Replace front brake pads and rotors under Full Maintenance Program
34210077MP	Service performed-brakes, rear
61610077MP	Replace wiper blade inserts
85990087MP	Early Oil Service (Annual for cars that don't require an oil service within a year)
85990088MP	1200 mile service (M cars only)
85990089MP	Engine oil service
85990091MP	First Engine Oil Service, otherwise the code is 85990089MP
85990092MP	Inspection 1
85990093MP	Inspection 2

NOTE: The last two digits of the service code indicate the program under which the item is performed.

Latest Update: Feb 05, 2005, 9:45 a.m.