

BimmerMaintenanceLog 1 .ods - Microsoft

Home Insert Page Layout Formulas Data Review View

Cut Copy Paste Format Painter Clipboard

Calibri 11 A A

B I U Font

Wrap Text Merge & Center Alignment

General \$ % , .00 .00 Number

Conditional Formatting Format as Table Normal Calculations

A1 Job

	A	B	C	D	E	F	G
17	Four Wheel Alignment	55752	12/11/2007				
18	Brake Fluid Flush	55752	12/11/2007				
19	Coolant Flush	55752	12/11/2007				
20	I PURCHASED CAR	56928	4/1/2008	99			Pre-purchase inspection
21	Windshield	57500	4/15/2008	400			Replaced due to pre-existing crack.
22	Mirror replacement	59000	7/17/2008	125			Rearview mirror about to start leaking, replaced via Sybesma's electronics.
23	Service	61197	8/18/2008	120			Stealership check for subframe cracks
24	Oil Change	61201	8/18/2008	396.26	66201	2/18/2009	Change A/C final stage unit; Install front strut mount
25	Service	63552	12/24/2008	1189.65			Coolant fluid and reservoir; Rear brake pad/rotor; Microfilter; WiperBlades
26	Inspection I	64236	2/4/2009	2200.84			INSPECTION I/II equivalent; OILCHANGE; Transmission, differential oils; Replace FCABs; Valvecover gasket; sparkplug/fuel filter; Checked Valves, adjustment not needed
27	Service	66697	5/7/2009	324.81			Replace Exhaust Cam Sensor
28	Change Air Filter	66697	5/7/2009		86697	5/7/2010	Removed Streamline Airfilter
29	DME Recall	66745	5/12/2009				
30	Battery Change	66000	7/7/2009	120			
31	Oil Change	69893	9/11/2009	450	74893	3/11/2010	Changed Thermostat; Tuneup to include new spark plugs; mini-inspection
32	Subframe analysis	70000	12/22/2009	70			Engine check light at dealership, alternator needs replacement; Subframe inspected under class-action, found to be intact.
33	Alternator	70033	12/24/2009	446.23			Checked alternator tension pulley, bearings fine.
34	Oil Change	74003	9/3/2010	519	79003	3/3/2011	Changed Oil Level Sensor; Also Changed Engine Air Filter and Cabin Air Filter
35	Service	81100	7/22/2011	4254			Inspect I/II equivalent; New Tires/alignment; Vanos Solenoid; Power Steering High Pressure Lines; Differential (41K used); Brake flush; Cooland Flush; Oil Change; Front Left Wheel hub
36							

BimmerMaintenanceLog_1

Ready

SlimBrowser - E46Fa... Microsoft Excel - Bi...